

C.L. "BUTCH" OTTER – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Eider Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6826 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

April 9, 2007

Kaddy Fyfe, Administrator Willows, The 898 S Meridian St Blackfoot, ID 83221

License #: RC-626

Dear Ms. Fyfe:

On November 8, 2006, a life safety code survey was conducted at Willows, The. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Eric Mundell, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

ERIC MUNDELL

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

mullel

EM/sc

c:

Mark Grimes, Supervisor, Facility Fire Safety & Construction Program



JAMES E. RISCH -- Governor RICHARD M. ARMSTRONG -- Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-036 PHONE: (208) 334-636 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

November 20, 2006

Kaddy Fyfe, Administrator The Willows 898 S Meridian St Blackfoot, ID 83221 FILE COPY

Dear Ms. Fyfe:

On November 8, 2006, a life safety code survey was conducted at The Willows. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by December 8, 2006.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

PRINTED: 11/13/2006 FORM APPROVED Bureau of Facility Standards (X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED IDENTIFICATION NUMBER: 01 - ENTIRE BUILDING A. BUILDING B. WING 11/08/2006 13R626 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 898 S MERIDIAN ST WILLOWS, THE BLACKFOOT, ID 83221 (X5) COMPLETE SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION ID (X4) ID (EACH CORRECTIVE ACTION SHOULD BE (EACH DEFICIENCY MUST BE PRECEEDED BY FULL PRÉFIX PREFIX DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) R 000 **Initial Comments** The facility was found to be in substantial compliance with the fire and life safety requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on November 8, 2006. The surveyor conducting the survey was: Eric Mundell REHS Health Facility Surveyor Facility Fire Safety & Construction

Bureau of Facility Standards

TITLE

(X6) DATE



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888 ASSISTED LIVING Non-Core Issues Punch List

| Facility Name | Physical Address | Phone Number | |
|---|--|-----------------------|--|
| The Willows | 898 South Meridian | 782-1478 | |
| Administrator | City | ZIP Code | |
| Survey Feam Leader 7 Fyte | Blackfoot | 8322 | |
| Survey Team Leader J | Survey Type | Survey Date | |
| Eric man sell | Fin / Life Sulaty | Nov 8, 2006 | |
| NON-CORE ISSUES | | | |
| ITEM RULE# | DESCRIPTION | DATE RESOLVED | |
| 1 16.03.22.405.06 Man-made hazards: A low height, 4-strand barb win Dalayad | | | |
| | fence is provided on the South side of the facility 3/2/07 | | |
| T+ | It does not provide the recessary portection mile | | |
| against readents wandering to the Canaladjacent | | | |
| for the property. Fine height 32 inches; US Frand | | | |
| | nointenann! The mechanical ocom | had two holes 12/5/06 | |
| Cut in the gyps in beard that engre of wooden stude. | | | |
| 3 16.03.22.75003 Fuel-fired heating divice: A report was not maintaining 12/5/4 | | | |
| on hile at the facility showing the farnace had | | | |
| pen ingritule last inspection um done 2/245 | | | |
| which was our 12 months from date 9 sures. | | | |
| 4 16.03-22.750.06 -The | e automatic fire sprinkler sys | tim report 11/9/04 | |
| ha | a not mointained on file as | ogulred Em | |
| | | | |
| | | | |
| | | | |
| | of Facility Representative | | |
| | | | |